



C: Bow



A: Hull plates and encroaching sand



B: Boiler



Side scan image showing boiler and engine contacts

*Selected images are from approximate areas of the site. These are labelled by an appropriate letter*

