


A: Possible propellor shaft supports



B: Diver footage showing ribs





C: Side scan image showing ribs



D: Anchor winch

*Selected images are from approximate areas of the site.
These are labelled by an appropriate letter*



E: Bow